


# ***Swan Pond Site Pool Repairs***

---

Walpole, MA

Pictures taken on 12 May 2011







New Fence Installed



New Fence screens the Pool wall





New Fence is anchored to the Pool wall

